

## **Advanced Materials**

# Araldite® LY 3585\* / Aradur® 5049-1 CH\*

Araldite<sup>®</sup> LY 3585 is a low viscosity epoxy resin Aradur<sup>®</sup> 5049-1 is a hardener mixture of polyamines

APPLICATIONS	<ul><li>Recreational composites</li><li>Structural composites</li></ul>			
PROPERTIES	Easy-to-handle laminating system for the production of advanced composites lay-up by wet process.			
PROCESSING	Wet lay-up			
TYPICAL KEY DATA	Araldite® LY 3585			
	Aspect (visual)**	Clear liquid		
	Colour (Gardner, ISO 4630)	≤ 3**		
	Viscosity at 25 °C (ISO 12058-1)	6500 - 9000**	[mPa s]	
	Density at 25 °C (ISO 1675)	1.15-1.20	[g/cm <sup>3</sup> ]	
	Flash point (ISO 2719)	> 200	[°C]	
	Storage temperature (see expiry date on original container)	2 - 40	[°C]	
	Aradur <sup>®</sup> 5049-1			
	Aspect (visual)**	Brownish liquid		
	Viscosity at 25 °C (ISO 12058-1)	600 – 1200**	[mPa s]	
	Density at 25 °C (ISO 1675)	0.90-1.0	[g/cm <sup>3</sup> ]	
	Flash point (ISO 2719)	115	[°C]	
	Storage temperature (see expiry date on original container)	2 - 40	[°C]	
	** Specified data are on a regular basis analysed. Data which is described in this document as 'typical' is not analysed on a regular basis and is given for information purposes only. Data values are not guaranteed or warranted unless if specifically mentioned.			
STORAGE	Provided that the products described above are stored in a dry place in their original, properly closed containers at the above mentioned storage temperatures they will have the shelf lives indicated on the labels. Partly emptied containers should be closed immediately after use. Araldite <sup>®</sup> LY 3585 which has crystallized and looks cloudy can be restored to its original state by heating to 60 - 80 °C.			

<sup>\*</sup> In addition to the brand name product denomination may show different appendices, which allows us to differentiate between our production sites:

e.g, BD = Germany, US = United States, IN = India, CI = China, etc.. These appendices are in use on packaging, transport and invoicing documents.

Generally the same specifications apply for all versions. Please address any additional need for clarification to the appropriate Huntsman contact.



MIX RATIO	Components	Parts by weight	Parts by volume
	Araldite <sup>®</sup> LY 3585 Aradur <sup>®</sup> 5049-1	100 44	100 52
	We recommend that the components are weighed with an accurate balance to prevent mixing inaccuracies which can affect the properties of the matrix system. The components should be mixed thoroughly to ensure homogeneity. It is important that the side and the bottom of the vessel are incorporated into the mixing process. When processing large quantities of mixture the pot life will decrease due to exothermic reaction. It is advisable to divide large mixes into several smaller containers.		
INITIAL MIX VISCOSITY	[°C]		[mPa s]
(HOEPPLER, ISO 12058-1B)	at 25		2300 – 2800
POT LIFE	[°C)	,	[min]
(TECAM, 200 GR, 65 % RH)	at 25		70 – 90
GEL TIME		,	[min]
(HOT PLATE)	at 60 at 80 at 100		22 - 26 6 - 10 2 - 5
	The values shown are for small amounts of pure resin/hardener mix. In composite structures the gel time can differ significantly from the given values depending on the fibre content and the laminate thickness.		
TYPICAL CURE CYCLES			n at 80°C iin at 100°C in at 120°C

The optimum cure cycle has to be determined case by case depending on the processing and the economic requirements.



PROPERTIES OF THE CURED, NEAT FORMULATION (TYPICAL AVERAGE VALUES)			
GLASS TRANSITION TEMPERATURE (IEC 1006, DSC, 10 K/MIN)	Cure:	T <sub>G</sub> [°C]	
	7 min at 100°C	78 – 83	
	30 min at 100°C	78 – 83	
	5 min at 120°C	80 – 86	
	30 min at 120°C	82 – 88	
LAB SHEAR STRENGTH TEST ON	Cure:	[N/mm²]	
ALU GRINDED	16 min at 80°C	ca.15	
(ISO 4587)	7 min at 100°C	ca.16	
	5 min at 120°C	ca.17	



## **HANDLING PRECAUTIONS**

Personal hygiene		
Safety precautions at workplace		
protective clothing	overalls	
gloves	essential	
arm protectors	recommended when skin contact likely	
goggles/safety glasses	yes	
Skin protection		
before starting work	Apply barrier cream to exposed skin	
after washing	Apply barrier or nourishing cream	
Cleansing of contaminated skin		
	Dab off with absorbent paper, wash with warm water and alkali-free soap, then dry with disposable towels. Do not use solvents	
Disposal of spillage		
	Soak up with sawdust or cotton waste and deposit in plastic-lined bin	
Ventilation		
of workshop	Renew air 3 to 5 times an hour	
of workplaces	Exhaust fans. Operatives should avoid inhaling vapours	

### **FIRST AID**

Contamination of the eyes by resin, hardener or mix should be treated immediately by flushing with clean, running water for 10 to 15 minutes. A doctor should then be consulted. Material smeared or splashed on the skin should be dabbed off, and the contaminated area then washed and treated with a cleansing cream (see above). A doctor should be consulted in the event of severe irritation or burns. Contaminated clothing should be changed immediately. Anyone taken ill after inhaling vapours should be moved out of doors immediately. In all cases of doubt call for medical assistance.

### **Huntsman Advanced Materials** (Switzerland) GmbH

Klybeckstrasse 200 CH - 4057 Basel Switzerland

Tel: +41 (0)61 299 11 11 Fax: +41 (0)61 299 11 12

www.huntsman.com/advanced\_materials



Huntsman Advanced Materials warrants only that its products meet the specifications agreed with the user. Specified data are analysed on a regular basis. Data which is described in this document as 'typical' or 'guideline' is not analysed on a regular basis and is given for information purposes only. Data values are not guaranteed or warranted unless if specifically mentioned.

The manufacture of materials is the subject of granted patents and patent applications; freedom to operate patented

processes is not implied by this publication. While all the information and recommendations in this publication are, to the best of Huntsman Advanced Material's knowledge, information and belief, accurate at the date of publication, nothing herein is to be construed as a warranty, whether express or implied, including but without limitation, as to merchantability or fitness for a particular purpose. In all cases, it is the responsibility of the user to determine the applicability of such information and recommendations and the suitability of any product for its own particular purpose.

The behaviour of the products referred to in this publication in manufacturing processes and their suitability in any given

end-use environment are dependent upon various conditions such as chemical compatibility, temperature, and other variables, which are not known to Huntsman Advanced Materials. It is the responsibility of the user to evaluate the manufacturing circumstances and the final product under actual end-use requirements and to adequately advise and warn purchasers and users thereof.

Products may be toxic and require special precautions in handling. The user should obtain Safety Data Sheets from

Huntsman Advanced Materials containing detailed information on toxicity, together with proper shipping, handling and storage procedures, and should comply with all applicable safety and environmental standards.

Hazards, toxicity and behaviour of the products may differ when used with other materials and are dependent on manufacturing circumstances or other processes. Such hazards, toxicity and behaviour should be determined by the user and made known to handlers, processors and end users.

Except where explicitly agreed otherwise, the sale of products referred to in this publication is subject to the general terms and conditions of sale of Huntsman Advanced Materials LLC or of its affiliated companies including without limitation, Huntsman Advanced Materials (Europe) BVBA, Huntsman Advanced Materials Americas Inc., Huntsman Advanced Materials (UAE) FZE, Huntsman Advanced Materials (Guangdong) Company Limited, and Huntsman Advanced Materials

Huntsman Advanced Materials is an international business unit of Huntsman Corporation. Huntsman Advanced Materials trades through Huntsman affiliated companies in different countries including but not limited to Huntsman Advanced Materials LLC in the USA and Huntsman Advanced Materials (Europe) BVBA in Europe.

All trademarks mentioned are either property of or licensed to Huntsman Corporation or an affiliate thereof in one or more, but not all, countries.

Copyright © 2012 Huntsman Corporation or an affiliate thereof. All rights reserved.